

Pegasus Ultimate Power Box v2 small factor PC base plate installation

Package includes the following items:

1 x Baseplate
1 x Hook & loop strap
4 x M3.5 screws (old enclosure)
4 x M3 screws (new enclosure)



Step 1
Check which version of enclosure you have and use the appropriate screws.

Untie the two (2) top stock screws on each side, displayed by the black arrows (keep them in safe place as you don't need them anymore).

Use the M3.5 screws to attach the plate on top of the UPB.

Use the M3 bolts into the available threads pointed with arrows to attach the plate on top of the UPB. $\label{eq:control}$






 $\label{eq:Step 2} Step \ 2$ You can now mount you preferable Mini PC or RPI using bolts or the included strap.



Step 3
Place the baseplate on top of the UPBv2 and use the appropriate screws to securely lock it.



Make sure that the qap of the baseplate faces the side of USB ports.



You are ready to go !!!